

VERIFICATION STATEMENT

Statement No: N141JSJX Rev.01

FOR PERSONNEL TRANSFER NET BASKET, PERSONNEL TRANSFER WORK **BASKET**

Valid for products not subject to DNV GL classification requirements.

Particulars of Product

Product Name:	Personnel Transfer Basket 4 person sitting
Type designation:	
Application/context:	Personnel Transfer Net Basket, Personnel Transfer Work Basket
ID/Serial/Tag no:	4/8-131216-03-032
The product is intended for:	STOCK
Requirements are based on:	Norsok R-002

Deviations and limitations, if any, are stated on page 2 onwards.

Particulars of Vendor and Purchaser

Global Outsourcing ApS Vendor: Vendor reference: PO 20667 Safe Transfer A/S Purchaser: Purchaser reference:

Issued at Esbjerg Verification on 2018-05-01



for **DNV GL**

This document has been digitally signed and will therefore not have handwritten signatures

> Bjørnsson, Oddur Surveyor

Except for any liability caused by DNV GL's gross negligence or wilful misconduct, DNV GL's maximum cumulative liability arising out of or related to the use of or reliance on this document shall be limited to USD 300 000.

Form code: 71.07a Revision: 2017-01



www.dnvgl.com

Page 1 of 4

Statement No: N141JSJX

Rev.01

Verification extent and result

Verification extent:

At the request of Global Outsourcing/Safe Transfer the undersigned surveyor has performed the following:

20th of April 2018 Witness drop test of Personnel Transfer Basket at the premesis of Safe Transfer.

Review NDT reports after drop test.

24th of April Witness floating test of Personnel Transfer Basket at Esbjerg docks.

Verification result/comments:

Drop Test:

Transfer basket with weight of 2000kg (see picture 1) was lifted to the height of 82 cm from ground before being dropped. (See pictures 3 and 4). Drop test performed with no comments. Weight confirmed with calibrated load cell (see picture 2).

Measurements performed before and after loadtest. Deviations in measurements assumed due to uncertainty in precision of measurements. Clients measurements stamped as witnessed. Review of Force NDT report no. 152815 dated 2018-04-25 performed with no comments.

Floating test:

Floating test performed to verify that the basket can float in an upright position. Transfer basket was lowered into the water and 4 persons climbed into it.

It was confirmed that the basket can float in an upright position with weight of 4 persons inside the basket (see pictures 5 and 6).

Floating drop test:

Empty basket was also dropped (both upright and upside down) from approximately 1 meters height above the surface of the water to confirm that the basket could float in an upright position after hitting the water.

It was confirmed that the basket returned to an upright floating position after a short period.

This Verification Statement covers only the witnessing of the Drop test and floating test of the Transfer Basket.

Report

Form code: 71.07a Revision: 2017-01 www.dnvgl.com Page 2 of 4

Statement No: **N141JSJX**

Rev.01



Form code: 71.07a Revision: 2017-01 www.dnvgl.com Page 3 of 4

Statement No: **N141JSJX Rev.01**





Picture 5: Basket floating.

Picture 6: Basket floating.

Page 4 of 4 Form code: 71.07a Revision: 2017-01 www.dnvgl.com